



# WOODWORK INSTITUTE OF CALIFORNIA

P.O. Box 980247 ♦ West Sacramento, CA 95798-0247

3164 Industrial Boulevard ♦ West Sacramento, CA 95691-3473

Phone (916) 372-9943 ♦ Fax (916) 372-9950 ♦ E-Mail: wic@wicnet.org ♦ Internet: www.wicnet.org



## ERRATA LIST 2001 *Manual of Millwork*

**NOTE:** This Errata list was updated on March 31, 2002.

- Section 2:** Page 30, Item 5.17.2, the Non-Member inspection pricing for Arizona, California & Nevada has changed to \$1,000 and \$1,400.00 for Oregon, effective 3/1/02.
- Section 4:** Page 58, Table 4-1 under Dimensional Stability column: Particleboard-M2 should be 5; MDF should be 5; Hardwood Veneer should be 1; Softwood Veneer should be 1; Hardboard-Standard should be 5; Particleboard-MR should be 5; MDF-MR should be 5; Particleboard-FR should be 5.
- Page 61, Item 6.1.9 should read: "Fire retardant and/or moisture resistant particleboard core shall be dyed red or green respectively to indicate its special characteristic."
- Section 11:** Page 151, Item 6.2.13, should have bullets in all categories: Economy, Custom, and Premium.
- Section 13:** Page 190, Item 6.2.6, should not have a bullet in the Premium category.
- Page 190, Item 6.2.7, should not have a bullet in the Custom category.
- Section 14:** Page 214, Item 6.2.107, heading 'CONCEALED, EUROPEAN STYLE HINGES' has changed to 'GRADE II HINGES'.
- Page 214, Item 6.2.108, heading 'WRAP AROUND STYLE HINGES' has changed to 'GRADE I HINGES'.
- Section 15:** Page 231, Item 1.8, should read: ". . . (see page #371 of Appendix) . . ."
- Page 245, Item 6.2.86, heading 'CONCEALED, EUROPEAN STYLE HINGES' has changed to 'GRADE II HINGES'.
- Page 245, Item 6.2.87, heading 'WRAP AROUND STYLE HINGES' has changed to 'GRADE I HINGES'.
- Page 245, Item 6.2.88, should have bullets in all categories: Economy, Custom, Premium and Laboratory.
- Page 247, Item 6.2.109, should have bullets in all categories: Economy, Custom, Premium and Laboratory.
- Page 250, BACKS (Continued), the reference to "Continued" should not be there.
- Page 252, Item 6.2.195, 'Fastenders' should read 'Fasteners.'
- Page 254, Item 6.2.217, drawing is missing the horizontal lines. See identical drawing in Section 14 at page 224, Item 6.2.262.
- Page 254, Item 6.2.219, should read 'Warp and/ or twist of cabinet doors less than 1-3/8" in thickness shall not exceed that indicated in 6.2.220 below or a maximum of 1/4" in any single door.'
- Section 16:** Page 310, Item 6.2.58, should read ". . . page #234"
- Supplement 2:** Page 280, Drawings #189 & 191 along with their descriptions are reversed.
- Appendix:** Page 366, the second item under Reference Sources, has an incorrect Website address for the American Furniture Manufacturers Association (AFMA). The correct Website is www.afma4u.org.
- Page 368, under the heading DRAWER SLIDES, it should read . . . (Effective 2/19/02, testing shall be based on a minimum 18" drawer box length and slide length with a 12 month update allowance for existing 18" test listings).
- Page 377, last paragraph titled Building Materials List references Chapter 42 of the Uniform Building Code. This should be Chapter 23.
- Page 390, WIC - STC - II, reference to 8mm x 50mm metal dowel screws should read: ". . . 7mm x 50mm . . ."

---

### NORTH EAST CALIFORNIA & NORTHERN NEVADA

Grass Valley, Ca. ♦ (530) 273-4786 ♦ Fax (530) 273-6427

### OREGON

Belmont, Ca. ♦ (650) 637-9307 ♦ Fax (650) 637-9316

### SOUTH CENTRAL CALIFORNIA & SOUTHERN NEVADA

Palmdale, Ca. ♦ (661) 272-1438 ♦ Fax (661) 265-1614

### NORTH WEST CALIFORNIA

Castro Valley, Ca. ♦ (510) 888-1556 ♦ Fax (510) 888-1568

### SOUTH WESTERN CALIFORNIA

Laguna Woods, Ca. ♦ (949) 829-8375 ♦ Fax (949) 829-0953

### SOUTHERN CALIFORNIA & ARIZONA

San Diego, Ca. ♦ (619) 531-0040 ♦ Fax (619) 531-0041